




## Priest Lake Thorofare Improvements Project ITB 2020-001 Addendum No. 2


- Mandatory Pre-Bid Meeting Presentation Slides Plan Holders List •






















# <section-header><section-header><section-header><list-item><list-item><list-item><image>

## **Priest Lake History**



### Outlet Dam

6/24/2020


- Enhancements for Water Management
  - 1951 Timber Dam
  - 1979 Concrete Dam Reconstruction



### Thorofare Uses

- 1930's Dredging/Breakwater
  - Recreation
  - Industry Timber, Mining

5



Prebid Meeting

# The Problem – Water Management



Water Shortage Dry Years

3' Lake Level
Management


6/24/2020

60 cfs Instream Flows
 Priest River





Navigable Access to Upper Priest Lake


- Thorofare Shoaling
- Loss of Navigation
- Erosion Protection
- Timber Breakwater Deterioration



Prebid Meeting










### Project Overview – New Work

Existing Breakwater Demolition, Access Road, Stream Diversion & Water Management, New Stone Breakwater Structure, Dredging, Beneficial Re-use Dredged Materials (Aquatic & Upland), Surveying



### **Thorofare Conditions & Objectives**

MAY 29, 2017

Objective: Provide sustainable navigation into Thorofare for access between lower and upper Priest Lake

Condition: Combination riverine and coastal processes



### **Thorofare Conditions**

November 19, 2018 Lake Level Unregulated ~ 0.5' gage



16

### Thorofare Conditions – March 2005

- Shallow sand bar at the mouth on 3/15/2005, WL = 0.33' USGS Lake Gage
- Significant flow spreading & flow cutting into the sand bar and underneath the breakwater




### THOROFARE GEOMORPHOLOGY

- Sediment deposition is result of decreased transport capacity as low-gradient Thorofare meets zero-gradient lake and flow spreading through the breakwater.
- Deposition has been accentuated by three factors at the mouth:
- 1) Widening of Thorofare channel along Breakwater
- Reduced Thorofare discharge & velocity as water passes through or under existing timber breakwater
- Wind-driven sediments get pushed through and around the breakwater eastern end during periods of low Thorofare flow



### Thorofare & Lake Bathymetry

- Water depths at the Mouth outlined by black dashed line is mostly shallower than 3 ft, with many areas shallower than 1.5 to 2 ft
- Survey is circa 2017; additional shoaling has occurred since that time




17

18


6/24/2020

6/24/2020









### Project Overview – New Work

Existing Breakwater Demolition, Access Road, Stream Diversion & Water Management, New Stone Breakwater Structure, Dredging, Beneficial Re-use Dredged Materials (Aquatic & Upland), Surveying




### **Thorofare Access** LOT 10 ACCESS ROAD - SANDPIPER SHORES RD (LOOKING WEST) SANDPIPER SHORES ACCESS ROAD LOT 8 CONSTRUCTION ACCESS POINT - LOT 10 (LOOKING NORTHEAST) EXISTING CONCRETE BULKHEAD (TO BE PROTECTED) SANDPIPER SHORES RD TELET Access Road Precon survey requirements **Utility Protection Requirements** Bulkhead protection measures Road maintenance • LOT 10 Snow Plowing Site restoration


# Project Overview – Site Access


- Private HOA Easement
- Utility Protection Requirements; Variable along route
- Access and use of lake bed allowable within the limits of construction to be restored to
- pre-project conditions upon completion of work
- Low Water time period








# <section-header><list-item><list-item><list-item><list-item>














# Stockpiling and Placement Areas


- Lions Head
  Boat Ramp Trailerable boats only
- Huckleberry
  Up to 800 cy dredged material
- Bear Creek
  Temporary stone stockpile area




### REGULATORY PERMITTING





- Fish Recovery
  - No stranding of fish as part of stream diversion
  - No fish handling. Any fish observed during dewatering must be encouraged to leave the site voluntarily.
- Water Quality Monitoring
  - Turbidity Monitoring in Lake per water quality certification
- Onsite Aquatic vs. Upland Beneficial Re-use
   Specified volume for transport offsite for upland
  - Specified volume for transport offsite for upland reuse





IDAHO Water Resource Board		
Pre-Bid Meeting June 23, 2 11:30 a.m. – 1:00 p.m. MDT	020	
<ul> <li>ITB Bid Documents Review</li> <li>The IWRB is seeking qua interested firms to submi Priest Lake Outlet Dam I</li> </ul>	alified and experier it an ITB submittal p	iced respondents from backage to complete the
ITB Critical Dates:		
TIB Critical Dates:     EVENT	DATE	TIME
	<b>DATE</b> June 23, 2020	<b>TIME</b> 11:30 am – 1:00 pm MDT
EVENT		
EVENT Mandatory Pre-Bid Meeting Optional Onsite Pre-Bid	June 23, 2020	11:30 am – 1:00 pm MDT
EVENT Mandatory Pre-Bid Meeting Optional Onsite Pre-Bid Meeting	June 23, 2020 June 29, 2020	11:30 am – 1:00 pm MDT 9 am – 11 am PDT























# Plan Holders List-Priest Lake Thorofare Improvements Project

Strider Construction Co., Inc.		
Quigg Brothers, Inc.		
Advanced American Construction		
Pacific Pile & Marine		
Envirocon		
Goodfellow Bros.		
American Construction		
N.A. Degerstrom, Inc.		
Ronglins, Inc.		
Crux Diving, Inc.		
Syman Erosion & Sediment Control		
Selland Construction		
Northbank Civil & Marine		
Missoula Plans Exchange		
Halme Construction		
Wm. Winkler Company		
Builders Exchange of Washington, Inc.		
TML Construction, Inc.		
TCG, Inc.		
Max J. Kuney Company		
Ballard Marine Construction		
IMCO General Construction		
Versatile Industries, Inc.		
C.E. Kramer Crane & Contracting, Inc.		
Noble Excavating		