



IDAHO WATER RESOURCE BOARD

ITB 2020-001 Priest Lake Thorofare Improvement Project Q & A

Brad Little
Governor

Roger W. Chase
Chairman
Pocatello
District 4

Jeff Raybould
Vice-Chairman
St. Anthony
At Large

Vince Alberdi
Secretary
Kimberly
At Large

Peter Van Der Meulen
Hailey
At Large

Albert Barker
Boise
District 2

John "Bert" Stevenson
Rupert
District 3

Dale Van Stone
Hope
District 1

Jo Ann Cole-Hansen
Lewiston
At Large

1. What are the load limits on the bridge located near Lion Head Park?

Response: Contact Steve Klatt at Bonner County Road & Bridge Department; PH 208-255-5681, ext.1 and email: steve.klatt@bonnercountyid.gov. Steve is knowledgeable in the local road conditions and is responsible for helping maintain a portion of the east priest lake road. Mr. Klatt was a member of the Priest Lake Water Management Project Steering Committee.

2. How was the existing breakwater constructed and do you have any as-builts?

Response: Information on the past construction can be provided by Ken Hagman of Copper Bay Construction; contact information is PH 208-443-2193 and email: ken@copperbayconstruction.com. Ken and his construction company were involved in the past breakwater construction and Ken was a member of the Priest Lake Water Management Project Steering Committee. Ken also is a resource for local knowledge and information regarding road conditions, potential non-IDWR provided lake access points and local sources of rock and stone. Randy Ramey is another resource for local knowledge who is a resident of Sand Piper Shores community and was a member of the project Steering Committee. Randy's contact information is PH 509-993-4889 and email: randy@predevinc.com.

3. Are there other non-IDWR provided shore access points to the lake and work area?

Response: See response to prior question #3 on existing breakwater.

4. Are local accommodations in Sand Piper Shores if desired by a Contractor?

Response: Some residents within Sand piper shores may be interested in renting homes if needed by the Contractor. The contact for questions pertaining to the Sandpiper Shores HOA and potential housing rentals is Stephanie Coy, President, Sandpiper Shores HOA, at PH 509-624-5087.

5. What local rock sources are available in the nearby region?

Response: A number of rock sources exist within the Bonner County area within the vicinity of Priest Lake and Priest River. The sources have variable capability in meeting the specifications for rock type and size. The following is a graphic showing the locations of rock quarries within the project vicinity. These do not represent any source relative to a specific type of stone product called out in the Contract. The locations are provided as additional information for investigation by the Contractor

for their determination on meeting the requirements of the contract. A potential source is available at Bear Creek from a IDWR Idaho Department of Lands (IDL) mining lease for that location. Additional information will be forthcoming in an addendum regarding this potential IDL source.

